

Ask Jon Eakes

TIP: Picking up metal shavings from a drill.

Last Updated: Monday, January 15th, 2001, Created: Sunday, January 14th, 2001

Jim from Windsor, Ontario has a really good suggestion for getting metal shavings away from the area where you are drilling a hole. Simply place some magnets around the hole an inch or so away and the shavings will all fly away from the drilling area and collect on the magnets. It really works.

Keywords:

Drills, Power Tools, Techniques

Article 1134

www.joneakes.com